



# Product Support Notice

© 2022-2023 Avaya Inc. All Rights Reserved.

PSN # PSN027103u

Avaya Proprietary – Use pursuant to the terms of your signed agreement or company policy.

Original publication date: 12-Apr-22. This is Issue #2, published date: 16-Jan-23. Severity/risk level High Urgency Immediately

Name of problem PSN027103u - Avaya Solutions Platform 100 Series Dell® R640 Avaya Certified BIOS/Firmware Update, Version 10.2

### Products affected

Avaya Solutions Platform 100 Series Dell® R640

NOTE: Avaya Converged Platform (ACP) was rebranded to Avaya Solutions Platform(ASP) in December of 2019

### Problem description

**January 16, 2023 Update: Reference PSN027105u -- Avaya Solutions Platform 100 Series Dell® R640 Avaya Certified BIOS/Firmware Update, Version 11.0** for the latest BIOS/FW update available.

### Notes:

- Per Dell, firmware version 5.10.00.00 introduced HTTP/HTTPS connection changes that may impact user connections when specifying FQDN address. Please reference Dell Article Number [000193619](#) for additional details.
- Avaya certified BIOS/FW updates should be applied as soon as possible to ensure robust security protection, performance and defense against known issues. BIOS/FW versions should always be checked whenever any maintenance activity is being performed on the server. This would include but is not limited to application updates/upgrades, server swaps, server remastering, new installations. It is recommended that the BIOS/FW update be performed prior to any other activity.

Avaya is providing an approved/certified update bundle for BIOS and Firmware on the ASP 100 Series Dell® R640 servers. This is inclusive of ASP 110, ASP 120, ASP 130 with the *following exceptions* for ASP 110.

Code	Description
700514273	ASP 110 DELL R640 SRVR P5 EQX SNR
700514861	ASP 110 DELL R640 SRVR P5 ACCS

This bundle is designated **Version 10.2** and is customer installable.

Avaya Solutions Platform 100 Series Dell® R640 servers are supplied under OEM relationship and managed differently than commercially available servers from the vendor.

Support, warranty and repair are through Avaya’s processes, not through the OEM vendor’s support process.

ASP 100 Series Server configurations are engineered for specific application needs. No hardware substitutions or additions are allowed. Servers cannot be repurposed.

Lifecycle Hardware and BIOS and firmware updates are managed by the Avaya Common Server team in conjunction with application R&D teams.

**These servers must NOT be updated with BIOS or firmware updates from the vendor’s web site.**

**Only Avaya provided updates can be used. Updating directly from the vendor’s web site will result in an unsupported configuration.**

You should always utilize the Avaya certified, bundled release. Do NOT upgrade individual components. This ensures that components interoperate in the manner in which they have been tested.

### Resolution

#### Acquiring Update Tool

The ASP 100 Series Dell® R640 BIOS/Firmware update DVD is to be burned from the ISO file (**R640fw-v10.2.iso**) available from [plds.avaya.com](http://plds.avaya.com) via PLDS Download ID: **ASP000000011**.

Download the **R640fw-v10.2.iso** to your PC and burn the image to a DVD. Ensure that the checksum of the downloaded image matches what is posted on PLDS. Burning the ISO as an image will create a bootable DVD disc.

**Read through all steps below before inserting and running the BIOS/Firmware update disc that you have created.**

**It is always best practice to perform a complete backup of the system before any firmware or hardware maintenance.**

After executing the procedures, the following components will be updated to the versions contained on the v10.2 disc.

**ASP 100 Series Dell® R640 BIOS/Firmware update tool (v10.2) disc contains:**

<b>Device Information</b>	<b>Firmware package release name</b>	<b>Firmware Version</b>
iDRAC9 with Lifecycle Controller	iDRAC-with-Lifecycle-Controller_Firmware_WPNPP_LN64_5.10.30.00_A00.BIN	5.10.30.00
R640 BIOS	BIOS_8JY6W_LN64_2.14.2.BIN	2.14.2
PERC H730/H730P/H830 Mini/Adapter	SAS-RAID_Firmware_700GG_LN_25.5.9.0001_A17.BIN	25.5.9.0001
PERC H750 Adapter	SAS-RAID_Firmware_MDV5D_LN64_52.16.1-4405_A00.BIN	52.16.1-4405
Intel Gigabit 4P I350-t rNDC	Network_Firmware_3XVMN_LN_20.5.15_A00.BIN	20.5.15
Broadcom Gigabit Ethernet BCM 5720	Network_Firmware_DFF48_LN64_22.00.6.BIN	22.00.6
Intel X710, XXV710, and XL710 adapters	Network_Firmware_M20T0_LN_20.5.13_A00.BIN	20.5.13
CPLD firmware for PowerEdge R640	CPLD_Firmware_9N4DH_LN_1.0.6_A00.BIN	1.0.6
Dell SEP Firmware for 14G Servers	Firmware_VV85D_LN_4.35_A00_06.BIN	4.35
Dell 12Gb Expander Firmware for 14G Servers	Firmware_60K1J_LN_2.52_A00.BIN	2.52
HGST Cobra F 600GB HDD 12Gbps SAS 3.5 10K 512n HUC101860CSS200	SAS-Drive_Firmware_X4FMC_LN_FU45_A00.BIN	FU45
Firmware version FJ39 for HGST drives. Vendor model numbers HUC101830CSS204, HUC101812CSS204, and HUC101860CSS204	SAS-Drive_Firmware_8MDXT_LN_FJ40_A00.BIN	FJ40
Toshiba Phoenix M4 MU3 SSD ISE 1920GB 2.5 SAS 12Gbps 512nModel	SAS-Drive_Firmware_OR TJ1_LN_AS0B_A00.BIN	AS0B
Firmware version ST33 for Seagate drives. Vendor model numbers ST600MM0069 and ST1200MM0099	SAS-Drive_Firmware_22YC9_LN_ST34_A00.BIN	ST34
Firmware version EA04 for	SAS-Drive_Firmware_TGCJ8_LN_EA05_A00.BIN	EA05

Toshiba drives. Vendor model numbers AL14SEB030NY, AL14SEB060NY and AL14SEB120NY		
Toshiba AL14SE Lite SAS12 3.5 10K 512n (NS PD) Model Number: AL14SEB060N	SAS-Drive_Firmware_66RK9_LN_DH02_A00.BIN	DH02
Firmware version BS05 for Seagate HDD Thunderbug 2.5 SAS12 10K 512n drive. Vendor model numbers: ST600MM0238 and ST300MM0078	SAS-Drive_Firmware_2R4CX_LN_BS05_A00.BIN	BS05
TOSHIBA AL15SE ISE 2.5 600GB SAS12 10K 512N Model Number: AL15SEB060NY Vendor Number: HDEBL84DAB51	SAS-Drive_Firmware_0T1RG_LN_EF06_A00.BIN	EF06
Toshiba Phoenix M4 WI SSD ISE 400GB 2.5 SAS 12Gbps 512n Model	SAS-Drive_Firmware_1DJXX_LN_AS10_A00.BIN	AS10
OS COLLECTOR 6.0	Diagnostics_Application_0G1JH_LN64_6.0_A00_01.BIN	6.0
Dell Diagnostics to verify proper operation of the hardware. Enterprise UEFI Diagnostics	Diagnostics_Application_5TVPW_LN64_4301A61_4301.62_01.BIN	4301A61
OS Driver Pack for PowerEdge 14G servers. This Driver Pack contains applicable storage, NIC, and video drivers to support OS installation using the Dell Lifecycle Controller	Drivers-for-OS-Deployment_Application_F93HH_LN_21.07.06_A00.BIN	21.07.06
iDRAC Service Module (iSM) is a lightweight software service that better integrates operating system (OS) features with iDRAC and can be installed on Dell yx2x or later generation of PowerEdge servers.	Systems-Management_Application_31P9G_LN64_4.1.0.0_A00.BIN	4.1.0.0

**Gracefully shut down the server according to Application Procedures**


*It is always best practice to perform a complete backup of the system before any firmware or hardware maintenance.*

## Firmware Update Procedures

1. A Monitor, USB keyboard and mouse will be required to run the update tool.
2. Open DVD tray at server power up, insert the firmware update disc and close tray. Server will boot from update disc.
3. A hardware boot screen will first appear – note that the BIOS version displayed may vary depending on when the server was originally shipped.



4. By default, Dell Deployment Toolkit(DTK) will boot from DVD:



5. Booting the DTK can take up to 10 minutes. If the server does not boot from disc, verify that the disc is correctly inserted in the DVD drive (drive LED is intermittently active) and verify the media is burned correctly. Verify boot order has DVD drive before RAID controller. Once DTK has booted, an inventory of the server will be run to determine what packages should be installed. After inventory collection, DTK will begin updating eligible components that require an update. Package installation status is displayed. Ensure packages install successfully. Select <Enter> when all updates have run and the user is prompted to *Press Enter to reboot...* **Do not reboot the server until prompted.**

```
booting from cdrom with share_script as drn_files/apply_bundles.sh
mount /dev/cdrom /opt/dell/toolkit/systems
BUILD_NUMBER is matching ...
Valid DTK CD is found

Starting /run/initramfs/live/drn_files/apply_bundles.sh ...
warning: /opt/dell/toolkit/systems/RPMS/rhel7/yumrpms/dell-system-update-1.9.3.0-22.01.00.x86_64.rpm: Header U4 RSA/SHA512 Signature, key ID 34d8786f: NOKEY
Preparing... ##### [100%]
Updating / installing...
 1:dell-system-update-1.9.3.0-22.01.##### [100%]
Installing dell-system-update ...
warning: /opt/dell/toolkit/systems/RPMS/dell-system-update-1.9.3.0-22.01.00.x86_64.rpm: Header U4 RSA/SHA512 Signature, key ID 34d8786f: NOKEY
DSU installation successful ...
Starting dsu for Avaya Firmware Update v10.1
DELL EMC System Update 1.9.3.0
Copyright (C) 2014 -- 2022 DELL EMC Proprietary.
Public keys exists
Parsing configuration file...
Reading the catalog ...
Getting System Inventory ...
Determining Applicable Updates ...
Installing Drivers-for-OS-Deployment_Application_F93HH_LN_21.07.06_A00
Installed successfully
Installing Network Firmware_4JUHJ_LN_21.81.3
Installed successfully
Installing BIOS_76NC0_LN64_2.13.3
Installed successfully
Installing iDRAC-with-Lifecycle-Controller_Firmware_P8HC9_LN64_5.10.00.00_A00
Installed successfully
Please restart the system for successful update(s) to take effect
Done! Please run 'dsu --inventory' to check the inventory
Progress report is available at:/usr/libexec/dell_dup/DSU_STATUS.json
Exiting DSU!

drn_files/apply_bundles.sh execution is completed ....
Press Enter to reboot ...
```

6. If DTK runs, but no packages require updating, the following screen will be displayed with the message *No Applicable Update(s) Available*. Press <Enter> to reboot the server when prompted and check firmware versions. See section in this PSN on “Check Firmware Versions”.

```
booting from cdrom with share_script as drn_files/apply_bundles.sh
mount /dev/cdrom /opt/dell/toolkit/systems
BUILD_NUMBER is matching ...
Valid DTK CD is found


Starting /run/initramfs/live/drn_files/apply_bundles.sh ...
warning: /opt/dell/toolkit/systems/RPMS/rhel7/yumrpms/dell-system-update-1.9.3.0-22.01.00.x86_64.rpm: Header U4 RSA/SHA512 Signature, key ID 34d8786f: NOKEY
Preparing... ##### [100%]
Updating / installing...
 1:dell-system-update-1.9.3.0-22.01.##### [100%]
Installing dell-system-update ...
warning: /opt/dell/toolkit/systems/RPMS/dell-system-update-1.9.3.0-22.01.00.x86_64.rpm: Header U4 RSA/SHA512 Signature, key ID 34d8786f: NOKEY
DSU installation successful ...
Starting dsu for Avaya Firmware Update v10.1
DELL EMC System Update 1.9.3.0
Copyright (C) 2014 -- 2022 DELL EMC Proprietary.
Public keys exists
Parsing configuration file...
Reading the catalog ...
Getting System Inventory ...
Determining Applicable Updates ...
No Applicable Update(s) Available
Progress report is available at:/usr/libexec/dell_dup/DSU_STATUS.json
Exiting DSU!

drn_files/apply_bundles.sh execution is completed ....
Press Enter to reboot ...
```

7. If the DTK tool will not run, power-off server and remove power cord(s) for 1 minute. Re-insert power cords, power-up server and repeat firmware update process. Verify DVD media is in good condition and has been correctly burned. Verify boot order is set such that DVD drive is set before HDD. To verify boot order: when server is powering up select <F2>*System Setup/System BIOS/Boot Settings/Boot Sequence*. Verify Embedded SATA Port Optical Drive is first in

boot order followed by the RAID Controller. Adjust the boot order and save if necessary following on the screen directions.


8. If the BIOS was updated, after the reboot, the server will display the screen shown below.
  - a. DO NOT POWER DOWN THE SERVER.
  - b. WAIT for the BIOS update and any additional updates (CPLD) to complete.
  - c. Server may reboot multiple times.
  - d. **Do Not Power Down the server.**



9. Once firmware updates are completed and finalized select <F10> to enter the Lifecycle Controller to verify firmware updates.  
→ **DVD should be removed from the server at this point.** ←  
Remove update disc from DVD drive after packages have updated by pressing the eject button on the DVD drive tray.



10. If prompted, cancel out of the *Settings/Language and Keyboard* screen by pressing <esc>. Then select **Firmware Update/View Current Versions**:



11. Verify versions: BIOS = 2.14.2, Broadcom Gigabit Ethernet = 22.00.6, Integrated Remote Access Controller (iDRAC) = 5.10.30.00, Lifecycle Controller = 5.10.30.00, Intel Gigabit 4P I350-t rNDC = 20.5.15 (Cascade Lake v1 server) and PERC H730P Mini = 25.5.9.0001 (Cascade Lake v1 server), PERC H750 Adapter = 52.16.1-4405 (Cascade Lake v2 server). Additional packages (i.e. OS Collector 14G, System CPLD, etc.) may update also depending on the vintage of server being updated.

### Cascade Lake v2 Server type

(updated configuration with H750 RAID controller and 4x1GbE Broadcom Network Daughter Card):

Firmware Update		
View Current Versions		
Component Name	Version	Date and Time
Backplane 1	4.35	2020-11-30 17:26:41
BIOS	2.14.2	2022-07-15 22:00:56
Broadcom Gigabit Ethernet BCM5720 - 34:73:5A:A0:11:08	22.00.6	2022-07-15 21:57:52
Broadcom Gigabit Ethernet BCM5720 - 34:73:5A:A0:11:09	22.00.6	2022-07-15 21:57:53
Broadcom Gigabit Ethernet BCM5720 - 34:73:5A:A0:11:0A	22.00.6	2022-07-15 21:57:51
Broadcom Gigabit Ethernet BCM5720 - 34:73:5A:A0:11:0B	22.00.6	2022-07-15 21:57:51
Broadcom Gigabit Ethernet BCM5720 - B0:26:28:14:D5:FA	22.00.6	2022-07-15 21:57:53
Broadcom Gigabit Ethernet BCM5720 - B0:26:28:14:D5:FB	22.00.6	2022-07-15 21:57:54
Dell 64 Bit uEFI Diagnostics, version 4301, 4301A61, 4301.62	4301A61	2022-06-02 03:59:20
Dell EMC iDRAC Service Module Embedded Package v3.5.0, A00	3.5.0	2020-08-03 23:06:57
Dell OS Driver Pack, 21.07.06, A00	21.07.06	2022-06-02 04:03:55
Disk 0 in Backplane 1 of RAID Controller in Slot 1	EF06	2022-05-11 00:15:56
Disk 1 in Backplane 1 of RAID Controller in Slot 1	EF06	2022-05-11 00:15:56
Disk 2 in Backplane 1 of RAID Controller in Slot 1	FU45	2022-05-11 00:15:56
Disk 3 in Backplane 1 of RAID Controller in Slot 1	FU45	2022-05-11 00:15:56
Disk 4 in Backplane 1 of RAID Controller in Slot 1	FU45	2022-05-11 00:15:56
Disk 5 in Backplane 1 of RAID Controller in Slot 1	FU45	2022-05-11 00:15:56
Identity Module (Y5KNV)	2.00	2020-08-03 23:06:58
Integrated Remote Access Controller	5.10.30.00	2022-07-15 21:39:59
Lifecycle Controller	5.10.30.00	2022-07-15 21:40:04
OS COLLECTOR, v6.0, A00	6.0	2021-06-11 21:18:48
PERC H750 Adapter	52.16.1-4405	2022-07-15 21:57:51
Power Supply.Slot.1	00.1B.53	2020-08-03 23:06:54
System CPLD	1.0.6	2020-08-03 23:06:57

## Skylake and Cascade Lake v1 Server type

(original configuration with H730P RAID controller and 4x1GbE Intel Network Daughter Card):

Lifecycle Controller			Help	About	Exit
<b>Firmware Update</b>					
View Current Versions					
Component Name	Version	Date and Time			
BIOS	2.14.2	2022-07-15 17:27:29			
Backplane 1	4.35	2020-11-30 16:26:40			
Broadcom Gigabit Ethernet BCM5720 - B0:26:28:14:57:E8	22.00.6	2022-07-15 17:27:28			
Broadcom Gigabit Ethernet BCM5720 - B0:26:28:14:57:E9	22.00.6	2022-07-15 17:27:30			
Dell 64 Bit uEFI Diagnostics, version 4301, 4301A66, 4301.67	4301A66	2022-03-03 17:48:02			
Dell EMC iDRAC Service Module Embedded Package v3.5.0, A00	3.5.0	2020-03-06 16:55:52			
Dell OS Driver Pack, 21.10.01, A00	21.10.01	2022-03-03 17:51:53			
Disk 0 in Backplane 1 of Integrated RAID Controller 1	ST34	2022-04-20 17:08:41			
Disk 1 in Backplane 1 of Integrated RAID Controller 1	ST34	2022-04-20 17:08:41			
Disk 2 in Backplane 1 of Integrated RAID Controller 1	ST34	2022-04-20 17:08:42			
Disk 3 in Backplane 1 of Integrated RAID Controller 1	ST34	2022-04-20 17:08:42			
Disk 4 in Backplane 1 of Integrated RAID Controller 1	ST34	2022-04-20 17:08:42			
Disk 5 in Backplane 1 of Integrated RAID Controller 1	ST34	2022-04-20 17:08:42			
Identity Module(FX4KG)	3.00	2020-01-08 18:34:52			
Integrated Remote Access Controller	5.10.30.00	2022-07-15 16:31:38			
Intel(R) Gigabit 4P I350-t rNDC - E4.43.4B:1D:80:D8	20.5.15	2022-07-15 17:27:31			
Intel(R) Gigabit 4P I350-t rNDC - E4.43.4B:1D:80:D9	20.5.15	2022-07-15 17:27:33			
Intel(R) Gigabit 4P I350-t rNDC - E4.43.4B:1D:80:DA	20.5.15	2022-07-15 17:27:35			
Intel(R) Gigabit 4P I350-t rNDC - E4.43.4B:1D:80:DB	20.5.15	2022-07-15 17:27:37			
Lifecycle Controller	5.10.30.00	2022-07-15 16:31:43			
OS COLLECTOR, v6.0, A00	6.0	2021-03-08 20:52:46			
PERC H730P Mini	25.5.9.0001	2022-03-02 13:47:27			
Power Supply.Slot.1	00.1B.53	2018-10-02 07:28:59			
Power Supply.Slot.2	00.1B.53	2018-10-02 07:28:59			
System CPLD	1.0.6	2019-10-17 17:09:49			

- After verifying the version information, select **Exit** in the upper right corner of the screen and then <YES> to reboot the server.
- If a firmware package did not install, power-off the server and remove power cord(s) for 1 minute. Re-insert power cords, power-up server and repeat firmware update process.

### Workaround or alternative remediation

N/A.

### Remarks

November 22, 2022: Issue 1.

January 16, 2023: Issue 2-- Updated to reference PSN027105u as the latest BIOS/FW available.

## Patch Notes

### Backup before applying the patch

Always.

### Download

N/A.

### Patch install instructions

N/A.

### Service-interrupting?

Yes

### Verification

N/A.

### Failure

N/A.



Patch uninstall instructions

N/A.

## Security Notes

The information in this section concerns the security risk, if any, represented by the topic of this PSN.

Security risks

N/A.

Avaya Security Vulnerability Classification

N/A.

Mitigation

N/A.

**If you require further information or assistance, please contact your Authorized Service Provider or visit [support.avaya.com](https://support.avaya.com). There you can access more product information, chat with an Agent, or open an online Service Request. Support is provided per your warranty or service contract terms unless otherwise specified in the Avaya support [Terms of Use](#).**

**Disclaimer:** ALL INFORMATION IS BELIEVED TO BE CORRECT AT THE TIME OF PUBLICATION AND IS PROVIDED “AS IS”. AVAYA INC., ON BEHALF OF ITSELF AND ITS SUBSIDIARIES AND AFFILIATES (HEREINAFTER COLLECTIVELY REFERRED TO AS “AVAYA”), DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING THE WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE AND FURTHERMORE, AVAYA MAKES NO REPRESENTATIONS OR WARRANTIES THAT THE STEPS RECOMMENDED WILL ELIMINATE SECURITY OR VIRUS THREATS TO CUSTOMERS’ SYSTEMS. IN NO EVENT SHALL AVAYA BE LIABLE FOR ANY DAMAGES WHATSOEVER ARISING OUT OF OR IN CONNECTION WITH THE INFORMATION OR RECOMMENDED ACTIONS PROVIDED HEREIN, INCLUDING DIRECT, INDIRECT, CONSEQUENTIAL DAMAGES, LOSS OF BUSINESS PROFITS OR SPECIAL DAMAGES, EVEN IF AVAYA HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

THE INFORMATION PROVIDED HERE DOES NOT AFFECT THE SUPPORT AGREEMENTS IN PLACE FOR AVAYA PRODUCTS. SUPPORT FOR AVAYA PRODUCTS CONTINUES TO BE EXECUTED AS PER EXISTING AGREEMENTS WITH AVAYA.

All trademarks identified by ® or ™ are registered trademarks or trademarks, respectively, of Avaya Inc.  
All other trademarks are the property of their respective owners.